

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4410	DATE	Jan. 24, 2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Concerning a fuel tank, since cooling of resin molding process was not sufficient, it could cause molding failure at thread part for fuel pump installation and sealing performance could be deteriorated in condition that a fuel pump is installed.</p> <p>Therefore, it could cause fuel leakage from the affected area when fuel tank is full.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HA36S	ALTO	2016	9,595
HBD-HA36V			2,008
DBA-HE33S	ALTO LAPIN		6,009
DBA-HB36S	CAROL		1,077
		TOTAL	18,689