

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	4422	DATE	January 28 ,2019
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		<p>There is insufficient clearance between the mounting bolt on the lower side of the side guard stay and the brake pipe because of the inappropriate installation of the side guard stay on the left side of the vehicle which is used by driving schools for mid-sized truck driving license lessens.</p> <p>Therefore, there is a risk of brake fluid leakage due to the damaged brake pipe resulting from the interference between the mounting bolt and the brake pipe, if a user continues to drive the vehicle under such condition.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FSR90S2	"FORWARD"	2018	1
2PG-FSR90S2		2017~2018	5
		TOTAL	6