

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4424	DATE	January 31, 2019
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Transmission control computer with automatic transmission with vehicle, due to inappropriate crutch control program, if noise of range signal is detected while driving with D-position (including Manual mode), unintended crutch control may be operated. Therefore, the shock may occur with decelerating, in the worst case, losing the driving stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ND5RC	Mazda「Roadster」	2015-2018	4,906
5BA-ND5RC		2018	406
DBA-NDERC		2016-2018	2,755
5BA-NDERC		2018	540
		Total	8,607