

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 4 2 7	DATE	Jan. 31. 2018
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the alternator, due to insufficient durability of pulley bearing against drive belt tension, the bearing may be broken in vehicle usage. Therefore, the function to reduce engine rotational fluctuation was lost and the tension of drive belt increase transiently.</p> <p>If the vehicle continue to use in this condition, bracket of the power steering pump driven by the same drive belt is broken by fatigue caused by the belt tension. In the worst case, the assistance of power steering may be lost and steering operation force will be increased.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-VR2E26	N I S S A N N V 3 5 0 C A R A V A N	2 0 1 2 ~ 2 0 1 8	54,884
CBF-CS4E26			13,532
CBF-CS8E26			75
CBA-KS2E26			7,164
CBA-KS4E26			2,105
CBF-DS4E26			684
CBF-DS8E26			126
CBF-JVR2E26			I S U Z U C O M O
CBF-JCS4E26	23		
CBF-JDS4E26	1		
		TOTAL	78,851