

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4434	DATE	Jan. 31, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to a manufacturing process issue, connector terminals inside the EPS control unit may have insulation failure between terminals. When the insulation failure occurs, EPS warning lamp is illuminated and EPS assist is disabled, which requires higher steering effort.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK2	「IMPREZA」	2019	Approx.10
DBA-GK3		2019	Approx.10
DBA-GK6		2018-2019	Approx.20
DBA-GK7		2018-2019	Approx.20
DBA-GT2		2018-2019	Approx.20
DBA-GT3		2018-2019	Approx.10
DBA-GT6		2018-2019	Approx.10
DBA-GT7		2018-2019	Approx.30
DBA-GT3		「XV」	2018-2019
DBA-GT7	2018-2019		Approx.40
5AA-GTE	2018-2019		Approx.150
5BA-SK9	「FORESTER」	2018-2019	Approx.90
5AA-SKE		2018-2019	Approx.270
		TOTAL	Approx.780