

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4421	DATE	February 1, 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>①In the drive shaft of the agricultural tractor, some evaluation criteria are inappropriate, so strength is insufficient. Therefore, the yoke is damaged by fatigue, and in the worst case, the power can not be transmitted and there is a possibility that the driving may become impossible.</p> <p>②In the fuel cap of the agricultural tractor, because the shape is inappropriate, the fuel cap may not be tightened or the screw may be damaged if tightened firmly. Therefore, the fuel cap may come off and the fuel may leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
EDM-34L	「EG326」	2010~2013	815	①815 ②815
		2013~2014	181	①122 ②181
	「EG328」	2010~2013	682	①682 ②682
		2013~2014	164	①108 ②164
		2011~2013	147	①147 ②147
		2013~2014	26	①25 ②26
	「EG330」	2010~2013	2,230	①2,230 ②2,230
		2013~2014	687	①427 ②687
	「EG334」	2010~2013	2,130	①2,130 ②2,130
		2013~2014	805	①470 ②805
		2011~2013	465	①465 ②465
		2013~2014	113	①89 ②113
EDM-45L	「EG437」	2009~2013	1,031	①1,031
		2013~2014	148	①148
		2011~2013	236	①236 ②236
		2013~2014	82	①49 ②82
	「EG441」	2009~2013	1,166	①1,166
		2013~2014	197	①197
	「EG445」	2009~2013	1,069	①1,069
		2013~2014	194	①194
		2011~2013	267	①267 ②267
		2013~2014	101	①66 ②101
KDN-53L	「EG453」	2010~2013	576	①576
		2013~2014	166	①166
		2011~2013	422	①422 ②422
		2013~2014	428	①127 ②428
			TOTAL	14,528 ①13,424 ②9,981