

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4435	DATE	February.7, 2019
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	To the ABS (anti-lock brake system) modulator, a component part was assembled by using an assembling jig of not precisely the right shape, when aluminum fragments may have been generated. Should such aluminum fragments get caught in the check valve when the ABS activated, the front wheels or rear wheels could be locked up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MC51	「CBR250RR」	2018	277
2BL-SC54	「CB1300 SUPER FOUR」 「CB1300 SUPER BOLD' OR」	2018	44
2BL-RC82	「NM4」	2018	22
2BL-RC80	「VFR800X」	2018	12
2BL-RC79	「VFR800F」	2018	10
		TOTAL	365