

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4436	DATE	Feb. 7. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain valve train mechanism of engines, because the oil supply hole position of the rocker support is improper, the gap of the oil passage may become large, causing more oil to be accumulated in the head cover than necessary and the oil may pass around in the combustion chamber through the blowby piping. Therefore, the engine may burn due to poor lubrication of the oil, resulting the engine to be damaged in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FR1AHA 2PG-FR1AHG 2PG-FR1AHJ 2RG-FR1AHA 2RG-FR1AHG 2RG-FR1AHJ	[HINO Profia]	2017~2018	2,663	
2PG-FR1AJA 2RG-FR1AJG		2017~2018	96	
2PG-FS1AGA		2017~2018	981	
2PG-FS1AHA 2PG-FS1AHG 2PG-FS1AHJ 2RG-FS1AHA 2RG-FS1AHG 2RG-FS1AHJ		2017~2018	333	
2PG-FS1AJA		2017~2018	235	
2PG-FW1AHG 2PG-FW1AHJ 2RG-FW1AHG 2RG-FW1AHJ		2017~2018	6,137	
2PG-FW1AJG 2PG-FW1AJJ 2RG-FW1AJG 2RG-FW1AJJ		2017~2018	110	
		TOTAL	10,555	