

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4432	DATE	February 14,2019
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the electrical vacuum pump which supplies the negative pressure to the brake booster, due to incorrect bearings which have less durability than correct one were assembled into production, the bearing may seize up prematurely. As a result, the pump stops its operation with the brake warning lamp and the alarm. If it is used continually, it is caused a risk that longer braking distance with the increase of the brake pedal effort.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-U68V	「MINICAB-MiEV」	2018	81
ZAA-HD4W	「i-MiEV」	2018	22
		TOTAL	103