

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4444	DATE	February 14, 2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to the jig which holds the aluminum body of Hydraulic ABS (Antilock Brake System) unit is inappropriate shape, in some case, an aluminum burr may be formed at the time of assembling the component parts to the body of it. If the said aluminum burr is stuck into the check valve, front wheel or a rear-wheel might be locked.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DU11A	BURGMAN	2018	24
2BL-C533F	GSX-S750	2018	20
2BL-VP55B	SV650	2018	8
		TOTAL	52