

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	4431	DATE	Feb.15, 2019
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD		
DESCRIPTION OF DEFECT	<p>Due to improper length of the bolt for installing a fuel supply pump, what is optional equipment, on the fuel tank for our wheel crane, a tip of the bolt would be touched to the fuel tank.</p> <p>Therefore, it is possible that the fuel tank is broken with the bolt when the bolt is installed and/or during operation of the wheel crane. Then it cause oozing of fuel from the broken portion.</p>		
Countermeasure	<p>The bolt will be replaced with the improved one.</p> <p>The fuel tank will be replaced with a new one.</p>		
Method for informing the concerned parties	<ol style="list-style-type: none"> <li>1. Send the direct mail to users</li> <li>2. Visit the end user</li> <li>3. Inform official service network</li> <li>4. Stick the label No.4431 as the evidence of rework completion onto around cabin door striker.</li> </ol>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CM03	MK650	CM03-02018 April 25 <sup>th</sup> , 2018	1 unit
CM03L	MK650	CM03L-02016 ~ CM03L-02026 Sep. 15 <sup>th</sup> , 2016 ~ Apr. 3 <sup>rd</sup> , 2018	3 units
TOTAL			4 units