## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /Import Vehicles

CAMPAIGN No.	Gai-2778	DATE	15/February/2019		
MANUFACTURER	Automobiles Volvo Car Corporation				
	(Japanese Importer: Volvo Car Japan Limited)				
DESCRIPTION OF	Icing between inner and outer plastic tubes may result in clip				
DEFECT	failure on outer tube.				
	Broken clips may end up in dislocation of the plastic outer tube				
	resulting in reduced structural strength of the POT unit. When				
	operated, reduced structural strength may result in complete				
	separation with freely expanding spring.				
	The corrective action	n is to replace Power	Operated Tailgate		
	lifting arms.				

	<del>_</del>			
	COMMERCIAL	MO	DEL	NUMBER OF
TYPE	NAME	Y	EAR	VEHICLE
		REC	ALLED	
VOLVO	- FACOUS			174 071
V0LV0	[XC60]	2018-2019		174, 871
		I		
			TOTAL	174, 871