
VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2784	DATE	Feb. 22, 2019
MANUFACTURER	DUCATI MOTOR HOLDING SpA		
	(Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	In the hose connection part of the engine oil cooler, some of the strengths		
	are insufficient due to insufficient analysis and testing of vibration.		
	Therefore, the connecting portion is damaged due to running vibration,		
	and in the worst case, the engine oil may leak.		
	The official Ducati dealer	will replace the oil of	cooler. This will be performed
	free of charge.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA01J	Panigale V4	2018-2019	99
2BL-DA01J	Panigale V4 S	2018-2019	238
2BL-DA01J	Panigale V4 Speciale	2018-2019	53
		TOTAL	390