

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2785	DATE	Feb. 22, 2019
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>Since the setting of the tightening torque of the cam chain tensioner attached to the cylinder block is set low, the tensioner may loosen due to running vibration. Therefore, engine oil in the cylinder block may leak.</p> <p>The official Ducati dealer will tighten the cam chain tensioner with the proper torque. This will be performed free of charge.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA01J	Panigale V4	2018-2019	99
2BL-DA01J	Panigale V4 S	2018-2019	243
2BL-DA01J	Panigale V4 Speciale	2018-2019	57
TOTAL			399