

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2791	DATE	Feb. 22, 2019
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>1) Because the strength study of the exhaust manifold is insufficient, it can not withstand pressure fluctuation of the exhaust gas during high load operation, the exhaust manifold may be damaged, and the exhaust gas may leak.</p> <p>2) Because the strength of the wire that activates the exhaust valve is insufficient, there is a case where the wire fixing position shifts. Therefore, the exhaust valve does not operate properly, the warning lamp lights up, the exhaust noise increases, and in the worst case, the safety standard may not be satisfied.</p> <p>The official Ducati dealer will replace the exhaust manifold and bowden cables for exhaust valve with a countermeasure. This will be performed free of charge.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA01J	Panigale V4	2018-2019	34
2BL-DA01J	Panigale V4 S	2018-2019	91
		TOTAL	125