

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2793	DATE	Mar. 13, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Fluctuations in the tightening torque of the bolts securing the fuel rail. Individual bolts may loosen over time.  The bolted connections for the fuel rail must be tightened.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8WCVN	A4 1.4T	2017	578
		Total	578