VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4459	DATE	March 14 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On emergency vehicles, due to the insufficient design of the siren amplifier power switch, when operating the power switch, the switch may remain pressed and do not return to original position. If this condition may occur, the siren amplifier does not work, resulting the rooftop beacon lights and the siren may become inoperative.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SDG-LR290J1	[ERGA MIO]	2016	12
		TOTAL	12