

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 4 6 2	DATE	Mar. 14. 2019
MANUFACTURER	AUTECH JAPAN INCORPORATED		
DESCRIPTION OF DEFECT	On emergency vehicles, due to the insufficient design of the siren amplifier power switch, when operating the power switch, the switch may remain pressed and do not return to original position. If this condition may occur, the siren amplifier does not work, resulting the rooftop beacon lights and the siren may become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-C26	SERENA	2016	16
		TOTAL	16