

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	4464	DATE	MAR. 14,2019
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.		
DESCRIPTION OF DEFECT	On emergency vehicles, due to the insufficient design of the siren amplifier power switch, when operating the power switch, the switch may remain pressed and do not return to original position. If this condition may occur, the siren amplifier does not work, resulting the rooftop beacon lights and the siren may become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-FEB90	CANTER	2016	9
		TOTAL	9