

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4466	DATE	March.14, 2019
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	To the ABS (anti-lock brake system) modulator, a component part was assembled by using an assembling jig of not precisely the right shape, when aluminum fragments may have been generated. Should such aluminum fragments get caught in the check valve when the ABS activated, the front wheels or rear wheels could be locked up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MC51	「CBR250RR」	2018	2
		TOTAL	2