

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2803	DATE	March 14 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Possible oil residue on the nuts which the left and right tail lights are attached to the vehicle body, might cause cracks or breaks on the tail light holder. If cracks are available a loss of the rear light during driving can occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-JG15	BMW X1 sDrive 18i	2018	148
LDA-HT20	BMW X1 xDrive 18d	2018	613
ABA-JG20A	BMW X1 xDrive 20i	2018	35
		TOTAL	796