

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2808	DATE	March 15, 2019
MANUFACTURER	Rolls-Royce Motor Cars Ltd.		
DESCRIPTION OF DEFECT	A small number of Rolls-Royce Cullinan (RR31) vehicles have been identified as having a problem concerning the harness connection to the Active Crash Safety Module (ACSM). This could affect the correct activation of the front seat belt pre tensioner and if the vehicle was involved in a crash of sufficient severity the seat belt pre tensioner could be activated for the wrong front seat occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-664S	Rolls-Royce Cullinan	2019	2
		TOTAL	2