

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2807	DATE	March.20, 2019
MANUFACTURER	Honda Vietnam Co., Ltd.		
DESCRIPTION OF DEFECT	The LED control unit to control lighting of automotive LED lights may, due to improper setting of voltage to be applied to the dimmer switch, winker switch and hazard switch, cause oxides to form on the contact points of these switches, thereby increasing contact resistance. Should this happen, these switches would lose electrical continuity whereby high-beam headlights, turn signal lights and/or hazard warning lights could fail to come on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-JF56	「PCX」	2014~2017	66,626
JBK-KF18	「PCX150」		20,355
		TOTAL	86,981