

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2812	DATE	March 28, 2019
MANUFACTURER	HONDA CANADA INC.		
DESCRIPTION OF DEFECT	In certain vehicles, driver's SRS airbag inflator, which was manufactured with moisture absorbed into desiccant, may have been assembled. Gas generating propellant in such an inflator may progressively deteriorate as a result of repeated fluctuations in ambient temperature and deteriorated gas generating propellant can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the inflator container could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-RL1	「LAGREAT」	2001～2004	1,629
UA-YD1	「MDX」	2003～2004	670
CBA-YD1		2004～2006	345
		TOTAL	2,644