

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 2814	DATE	10 April, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a missing assignment within the instrument cluster's software, the red brake warning light is not activated when the brake pads are worn out. Only the yellow information is shown in the multi-functional display, which can be confirmed and suppressed until the next ignition switch.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-G2H29A	Panamera 4S	2017	217
ABA-G2H29AX			1
ABA-G2H40A	Panamera Turbo		109
ABA-G2H40AX			8
ABA-G2H30A	Panamera		85
	Panamera 4		24
ABA-G2H30AX			1
ALA-G2H29A	Panamera 4 e-hybrid		30
ALA-G2J29A			1
ABA-G2J29A	Panamera 4S		2018
ABA-G2J29AX		8	
ABA-G2J40A	Panamera Turbo	146	
ABA-G2J40AX		2	
ABA-G2J30A	Panamera	333	
	Panamera 4	237	
ABA-G2J30AX		21	
ALA-G2J29A	Panamera 4 e-hybrid	218	
ALA-G2J29AX		12	
ALA-G2J40A	Panamera Turbo S	56	
ALA-G2J40AX		7	

ABA-E3K29	Cayenne S	2019	12
ABA-E3K29A			55
ABA-E3K30	Cayenne		11
ABA-E3K30A			39
ABA-E3K40A	Cayenne Turbo		38
Total			1888