

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4470	DATE	April 11,2019
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the auto adjusting structure for the clearance between the shoe and the drum of the rear brake, grease is not applied to the screw surface of the adjuster bolt due to improper grease coating during the parts assembly process. If a vehicle with this condition is used over time, the screw surface may get rusty and stuck, possibly resulting in malfunction of the auto adjusting structure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2016-2017	26,012
DBA-LA160S			5,890
DBA-LA250S	CAST	2016-2017	23,569
DBA-LA260S			5,064
DBA-LA360S	Mira e:s	2017	2,125
DBA-LA600S	TANTO	2016-2017	69,607
DBA-LA610S			14,345
DBA-LA700S	WAKE	2016-2017	15,090
DBA-LA710S			2,979
DBA-LA800S	MOVE canbus	2016-2017	36,355
DBA-LA810S			7,843
HBD-LA700V	HIJET Caddie	2016-2017	759
HBD-LA710V			255
EBD-S500P	HIJET TRUCK	2016-2017	11,121
EBD-S510P			30,721
DBA-M700S	Boon	2016-2017	1,389
DBA-M710S			418

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-M900S	THOR	2016-2017	6,506
DBA-LA250A	PIXIS JOY	2016-2017	3,142
DBA-LA260A			825
DBA-LA360A	PIXIS EPOCH	2017	44
DBA-LA700A	PIXIS MEGA	2016-2017	3,043
DBA-LA710A			641
EBD-S500U	PIXIS TRUCK	2016-2017	623
EBD-S510U			1,535
DBA-M700A	PASSO	2016-2017	24,261
DBA-M710A			4,353
DBA-M900A	ROOMY/TANK	2016-2017	63,256
DBA-LA150F	STELLA	2016-2017	2,726
DBA-LA160F			1,432
DBA-LA360F	PLEO PLUS	2017	227
DBA-LA600F	CHIFFON	2016-2017	3,864
DBA-LA610F			1,591
EBD-S500J	SAMBAR TRUCK	2016-2017	684
EBD-S510J			3,242
DBA-M900F	JUSTY	2016-2017	2,117
		TOTAL	377,654