

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4471	DATE	April 11,2019
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to improper waterproof treatment on the fitting section between the cowl louver and the dash panel, rain water may leak into the brake booster and cause it to rust. If a vehicle with this condition is used over time, rust may quickly develop. In the worst case, a hole may open in the brake booster, possibly resulting in the increase of the brake pedal effort and a longer braking distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-LA100S	MOVE	2010-2014	413,821
DBA-LA100S			
CBA-LA110S			
DBA-LA110S		2014-2018	83,366
DBA-LA150S			245,491
DBA-LA160S			53,522
DBA-LA600S	TANTO	2013-2016	471,841
DBA-LA610S			90,792
DBA-LA700S	WAKE	2014-2016	76,124
DBA-LA710S			16,233
HBD-LA700V	HIJET Caddie	2016	2,117
HBD-LA710V			362

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-LA100F	STELLA	2011-2014	54,028
DBA-LA100F			
CBA-LA110F			
DBA-LA110F		2014-2018	19,441
DBA-LA150F			27,664
DBA-LA160F			12,535
DBA-LA700A	PIXIS MEGA	2015-2016	6,641
DBA-LA710A			1,401
		TOTAL	1,575,379