

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic vehicles

CAMPAIGN No.	4475	DATE	April.11.2019
MANUFACTURER	M-TEC Co., Ltd.		
DESCRIPTION OF DEFECT	The front damper assemblies may have insufficient durability due to an inappropriate material and/or shape of the damper shaft. Therefore, when the steering operation is repeated, which can eventually causes the break of the damper shaft and, if the worse came to the worst, the vehicle could lose the running stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JW5	S660 MUGEN RA	2016~2017	661
		TOTAL	661