

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4479	DATE	Apr.11.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On the ambulances, due to improper surface treatment of a component inside the back door lock, there is a possibility that, when the back door is repeatedly opened and closed, the component could wear prematurely. If this were to occur, the warning light will illuminate and the back door may become half-open on the condition such as vibration during vehicle use, resulting in noncompliance with the requirement prescribed in “Safety Regulations for Road Vehicles”, Article 25 (requirement of entry doors).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBF-TRH221S	[TOYOTA AMBULANCE]	2012-2018	248
CBF-TRH226S			2,850
		TOTAL	3,098