

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 4 8 0	DATE	April. 11. 2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the spiral cable on steering wheel for taxi specification vehicle, due to improper structure of holding the wiring, the wiring may contact to inner parts in large turn of steering wheel. Therefore, the wiring may be worn down due to repetition of the large turn. In worst case, the wiring may be broken and then the horn may not work or airbag warning lamp may turn on by wiring breakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-M20	NV200 VANETTE NV200	2010 ~ 2016	1, 588
		TOTAL	1, 588