

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4484	DATE	April 11, 2019
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Engine timing belt may, due to inadequacies in the process of manufacture of the belt, be lacking in strength of the belt teeth. If the vehicle fitted with such a timing belt continues in service, the belt teeth can eventually be damaged whereby the warning light/indicator would come on and, in the very worst case, the engine could stall and refuse to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-KC2	「LEGEND」	2018	243
		TOTAL	243

Vehicle to which the subject part (timing belt) was fitted for the purpose of periodic replacement or other servicing after the vehicle was manufactured.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-KC2	「LEGEND」	2015～2016	29
		2016	1
		TOTAL	30

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS
TIMING BELT KIT	06141-R9S-305	2018～2019	21
TIMING BELT	14400-R9P-A01	2018	3
		TOTAL	24