

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 4 6 1	DATE	2019.4.17
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO. ,LTD.		
DESCRIPTION OF DEFECT	There is a situation that the joint's shape of hydraulic hose between HST pump and motor is not adequate and the strength is insufficient on fluid power transmission unit of shovel loaders. There is a concern that the joint would be cracked by stress and frequency of operation. Also the joint could be broken off and the hydraulic oil would be leaked.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
L1DA	「V1-1A」	2007 to 2018	194
WA101E0	「WA10-1」	2007 to 2010	43
	「WA10-6」	2011 to 2018	180
TOTAL			417