

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4 4 8 6	DATE	April 17, 2019
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	In the harness of the agricultural tractor, the harness is in contact with the front tire when turning left because the wiring method of the harness is inappropriate. Therefore, the use in the condition may lead to be damaged, and in the worst case scenario, the lights do not light up or the engine stops and can not be restart.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「TJV885」	2018	1
—	「TJV755」	2018	2
		TOTAL	3