VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic vehicles

CAMPAIGN No.	4485	DATE	April 18,	2019
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	Thus, if the vehicle continues operation oil which may activate the oil pressure we the combustion chamber which may cau ② With regards to the alternator power sup side of the alternator, some of the power become damaged from vehicle vibration	ening parts of the pipe may have cracking under these conditions, the fuel may leak arning lamp/buzzer. In the worst case, the se increased engine speed unexpectedly	caused by stress from er into the cylinder head and e diluted engine oil may b buting and attachment me pracket edge and the will under these conditions, the	ngine vibration. Id dilute the engine e pumped up to thod for the back re cover may
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5AL	QUON	2017 - 2018	12	① 12
2PG-CD5BA		2017 - 2018	105	① 105 ② 7
2PG-CD5BL 2PG-CD5BL Kai		2017 - 2018	119	① 119 ② 2
2PG-CD5CA 2PG-CD5CA Kai		2017 - 2018	2,082	① 2,082 ② 208
2PG-CD5CE		2018	138	① 138 ② 17
2PG-CD5CL		2017 - 2018	162	① 162 ② 2
2DG-CF5AL		2018	47	① 47 ② 32
2PG-CG4CA		2018	1	① 1
2PG-CG5BA		2017 - 2018	29	① 29 ② 2
2PG-CG5BE 2PG-CG5BE Kai		2018	4	① 4
2PG-CG5BL		2018	2	① 2
2PG-CG5CA		2017 - 2018	3,605	① 3,605 ② 158
2PG-CG5CE		2018	167	① 167 ② 16
2PG-CG5CL		2017 - 2018	144	① 144 ② 10
2PG-CW4AL		2018	2	① 2
2PG-CW5AL		2017 - 2018	842	① 842
2PG-CW5BL 2PG-CW5BL Kai		2017 - 2018	184	① 184 ② 28
2PG-CW5CA 2PG-CW5CA Kai		2017 - 2018	136	① 136 ② 8
2PG-CW5CL Kai		2017 - 2018	197	① 197 ② 4
2PG-CX5BA		2017 - 2018	58	① 58 ② 24
2PG-CX5BL		2017 - 2018	36	① 36 ② 2
2DG-CZ5BL 2DG-CZ5BL Kai		2018	168	① 168 ② 112
2PG-GK5AAB 2PG-GK5AAB Ka	i	2017 - 2018	995	① 995 ② 4
2PG-GK5AAD		2017 - 2018	394	① 394 ② 5
2PG-GK5AAE		2017 - 2018	73	① 73
2PG-GK5AAK		2018	1	① 1
2DG-HF5AL	-	2018	2	① 2
2DG-HZ5BL		2018	3	① 3
2DG-SF5AL	-	2018	2	① 2
2DG-SZ5BL		2018	4	① 4
	•	TOTAL	9,714	① 9,714 ② 641