

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2823	Date	April 18., 2019
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	A main power relay may have an internal short circuit due to material migration. Once the defect appears, machine control will be lost immediately or termal incident occurs.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-KNP	「914G2」	2012-2014	75
EDR -JTM	「924H」	2012-2013	9
EDR-PED	「924Hz」	2011-2013	102
WDR-PWR	「924K」	2013-2016	174
YDR-LTE	「926M」	2016	9
EDR-FTD	「930H」	2012-2013	58
WDR-RHN	「930K」	2013-2016	88
YDR-KTG	「930M」	2013-2016	5
WDR-SWL	「938K」	2013-2017	144
YDR-J3R	「938M」	2016	9
UDS-FER	「950K」	2013-2016	119
UDS-FLL	「962K」	2013-2016	24
		TOTAL	816