

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| CAMPAIGN No. | 4490 | DATE | 24-Apr-19 |
|-----------------------|---|---------------------|-------------------|
| MANUFACTURER | KUBOTA Corporation | | |
| DESCRIPTION OF DEFECT | At the fuel filter bracket of the agricultural tractor may be damaged due to lack of strength. Therefore, in the worst case, the fuel hose may be caught in the cooling fan and broken, so that the fuel may be scattered in the bonnet and white smoke (a mist of light oil) may be released from the engine room. | | |
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
| XDN-MRX YDN-MRX | MR60 MR60-PC | 2015~2019 | 320 |
| | MR65 MR65-PC | 2015~2019 | 750 |
| | MR70 MR70-PC | 2015~2019 | 709 |
| YDN-MWY | M720W | 2017~2019 | 162 |
| XDN-MRX YDN-MRX | GV60 GVK60 | 2015~2018 | 39 |
| | GV65 GVK65 | 2015~2019 | 58 |
| | GV70 GVK70 | 2015~2019 | 67 |
| | T2.65 | 2015~2019 | 319 |
| | | TOTAL | 2424 |