

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4 4 9 8	DATE	May 10, 2019
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>In the exhaust device of the load roller, there is a device which breaks the clamp and the bracket because the strength of the clamp for fixing the exhaust pipe and the bracket for fixing the clamp is insufficient.</p> <p>Therefore, if the use is continued as it is, a crack may occur in the exhaust pipe due to vibration or the like during traveling, and in the worst case, the exhaust gas may leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「SW504」	2018 — 2019	33
		TOTAL	33