VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4496	DATE	May.13 2019	
MANUFACTURER	KATO WORKS CO.,LTD.			
DESCRIPTION OF DEFECT	For the starter motor cable of the wheel crane, found that bending load might be applied to the cable terminal due to improper instruction for installation. Therefore, it might cause impossibility of starting the engine due to broken cable terminal caused by engine vibration, etc			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDR-KRC020	KRM-13H	2017~2018	115	
TOTAL			115	