

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4495	DATE	May 16, 2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper shape of the holes for rivets to fasten the component parts of the movable driven face, the rivet joint may be insufficient. If continued to use with this condition, excessive stress is applied to the rivet holes when accelerating. In worst case, the movable driven face may be broken resulting to the vehicle cannot be driven</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-CH41A	BURGMAN	2017-2019	1,862
		TOTAL	1,862