
VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4500	DATE	May. 16. 2019	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	On certain emission control devices of heavy-duty sightseeing buses, due to the improper wiring instructions for NOx sensor, upstream and downstream NOx sensor are connected in reverse order. Therefore, the emission control device may not function correctly, resulting emission gas not to satisfy safety regulations.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-RU2AHDA	[HINO Selega]	2017~2019	266
2KG-RU2AHDA		2017 = 2019	200
		TOTAL	266