

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2843	DATE	May 21 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the engine components, the firmware of the crankshaft sensor is improper, the position of the crankshaft is not properly detected and an erroneous signal is input to the engine control unit. Therefore, the fuel injection timing and the ignition timing cannot be accurately controlled, and the rotation of the engine becomes unstable. In the worst case, the engine may stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-JC20	BMW 523d	2018	12
DBA-JA20	BMW 530i	2018	4
CLA-JA20P	BMW 530e iPerformance	2018	5
DBA-JB30	BMW 540i	2018	3
DBA-JB30	BMW 540i xDrive	2018	1
TOTAL			25