

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2852	DATE	May 21 st , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to faulty encoding data in the headlight control unit, there is a malfunction in the front side marker lights. When the headlight is switched on, the side marker lights are incorrectly off, which does not comply with the safety regulation article 34.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-YS20	MINI JCW CrossoverA4	2017 - 2018	306
TOTAL			306