

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4499	DATE	May.22.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the headlamps of the subject vehicles, there is a possibility that, if the headlamps are activated continuously for a long period of time beyond supposition, such as in taxi use applications, the aluminum coating layer of the headlamp reflectors could peel over time from heat exposure and ultraviolet rays which are emitted from the headlamp bulbs. If the vehicle is continuously operated in this condition, the collection of light become insufficient and the luminous intensity of the headlamp could gradually decrease, and in the worst case, the luminous intensity may not comply with the requirement prescribed in “Safety Regulations for Road Vehicles”, Article 32 (requirement of headlamps).</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-GRS210	[CROWN]	2013-2015	27	for commercial use
DBA-GRS211		2013	6	
DBA-GRS214		2015	1	
DAA-AWS210		2013-2015	362	
DAA-AWS211		2014-2015	9	
		TOTAL	405	