

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2841	DATE	22/May/2019
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Some driving conditions may generate a soot build up on the front oxygen sensor, resulting in too long sensor response time. Check Engine Light will be lit. The corrective action is to download improved ECM software.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[S60]	2016-2018	1051
VOLVO	[V60]	2016-2018	3513
VOLVO	[XC60]	2016-2019	3647
VOLVO	[V60CC]	2016-2018	1033
VOLVO	[V90]	2019	332
VOLVO	[V90CC]	2019	230
VOLVO	[V40]	2016-2019	8034
VOLVO	[V40CC]	2016-2019	2670
		TOTAL	20,510