

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4504	DATE	May.29.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On a rear left side door glass, due to an improper program of production equipment, the glass may not be cooled and not meet the shredding requirements. If the glass was broken by external factors, the pieces may not become small enough, resulting in noncompliance with the requirement prescribed in "Safety Regulations for Road Vehicles", Article 29 (requirement of window glasses).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-KSP130	[Vitz]	2019	710	The subject vehicles are equipped with tempered door windows
DBA-NSP130			682	
DBA-NSP135			242	
DBA-NCP131			33	
DAA-NHP130			502	
		TOTAL	2,169	