

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2848	Date	May 29, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the head restraint of the rear seat, the mounting strength is insufficient due to inappropriate welding between the head restraint guide and the seat back frame. As a result, the shock may cause the weld to break, and the head restraint may come off, making it impossible to effectively suppress excessive backward tilt of the head of the passenger.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AUCJZ	Golf 1.2/77kW	MY2018	223
DBA-AUCPT	Golf 1.4/103kW	MY2018	191
ABA-AUCHH	Golf GTI/162kW	MY2018	109
ABA-AUDJHF	Golf R2.0/228kW	MY2018	63
ABA-AUCJXF	Golf R2.0/206kW	MY2018	7
DLA-AUCUK	Golf GTE	MY2018	5
ABA-3HDJHF	Arteon 2.0/206kW	MY2018	18
ZAA-AUEAZ	e-Golf/100kW	MY2018	13
		Total	629