

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2857	DATE	May 30, 2019
MANUFACTURER	Thai Honda Manufacturing Co.,Ltd.		
DESCRIPTION OF DEFECT	With respect to the snap ring securing the 5th gear to the mainshaft, the mainshaft grooving for the snap ring and the snap ring assembly jig may have been inadequate whereby the snap ring may not be fully seated in the groove. When shifted in such a condition, the 5th gear can slip out of place and produce unusual noise, and as the worst consequence the rear wheel could be locked up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MD49	「Rebel 250」	2018	2,653
2BK-MD44	「CRF250L」 「CRF250M」 「CRF250 RALLY」	2018	699
2BK-MC52	「CB250R」	2018	557
		TOTAL	3,909