

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4506	DATE	June 4 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>The subject matter relates to an engine mounted on light-duty trucks. Due to an inappropriately designed shape of its cylinder head cover, rainwater becomes trapped in its injector oil seal in certain circumstances. Consequently, the oil seal becomes swollen losing its sealing capability. Continuing use would result in engine oil leaks, and in the worst case there is a risk that the engine could be damaged.</p>	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-NKR88YN 2RG-NKR88YN	[ELF]	2018	133
2PG-NPR88YN 2RG-NPR88YN		2018	1,174
		TOTAL	1,307