

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

**Domestic Vehicles**

<b>CAMPAIGN No.</b>	<b>4508</b>	<b>DATE</b>	<b>Jun 6, 2019</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>Due to improper material for component parts were used in the rear brake light switch, the component parts in the switch will corrode by intrusion of water.</p> <p>Continued use in this condition, poor conductivity or short circuit will occurs in the brake switch circuit.</p> <p>In worst case, the break light will not activate or continue to lighting.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
<b>2BK-DN11A</b>	<b>GSX250R</b>	<b>2017-2019</b>	<b>4,337</b>
		<b>TOTAL</b>	<b>4,337</b>