VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4509	DATE	June 13, 2019	
MANUFACTURER	SUZUKI MO	TOR CORPOR	ATION	
DESCRIPTION OF DEFECT	Unintended activation of the side air bag, the curtain air bag and the seat belt pre-tensioner may occur, when the rear door is slammed shut, due to the improper program in the airbag controller. In the worst case, there is a risk of injury to the occupant during the airbag deployment.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-ZC83S			15,577
DBA-ZD83S			2,791
DAA-ZC53S		2016~2019	11,790
DAA-ZD53S	SWIFT		3,332
DBA-ZC13S			3,474
DAA-ZC43S		2017~2019	1,150
CBA-ZC33S		2017, 2019	13,703
		TOTAL	51,817